


ASSEMBLY INSTRUCTIONS

ME-T7010E1.29

ASSEMBLY INSTRUCTIONS




COMPONENTS CHECKLIST

TABLE TOP 1 PC	
SUPPORT PANEL 1PC	
LEG 4PCS	
SUPPORT RAIL : 4 PCS	
PEDESTAL 1 PC	
LEAF 1 PC	

FITTINGS HARDWARE


Part ' A '		Part ' B '	
JCBC BOLT M6 X 40 : 8PCS		SPRING WASHER 5/16" X 13.5 20 PCS	
Part ' C '		Part ' D '	
HEX NUT 5/16" X 12.7 12 PCS		SPANNER 13MM : 1 PC	
Part ' E '		Part ' F '	
BASE GLIDE M6 X 16 : 4PCS		FLAT WASHER 5/16" X 17 20 PCS	
Part ' G '		Part ' H '	
ALLEN KEY M4 : 1 PC		CHIPBOARD SCREW M4 X 32 4PCS	

STEP 1




STEP 2


STEP 2A




STEP 2B




STEP 3




STEP 4



STEP 5




LEAF OPENING INSTRUCTION



1

2

3



4

5